

Service Bulletins

- [iPod Nano Replacement](#)
- [EFI Update for Mac Pro and Xserve 2009](#)

iPod Nano Replacement



Dear iPod nano owner,

Apple has determined that, in very rare cases, the battery in the iPod nano (1st generation) may overheat and pose a safety risk. Affected iPod nanos were sold between September 2005 and December 2006.

This issue has been traced to a single battery supplier that produced batteries with a manufacturing defect. While the possibility of an incident is rare, the likelihood increases as the battery ages.



EFI Update for Mac Pro and Xserve 2009

Apple offers an EFI firmware update for Mac Pro and Xserve 2009:

This update addresses the following issues for Mac Pro (Early 2009) computers:

- Improves compatibility with virtualization products utilizing VT-d
- Improves storage performance under Windows XP for Boot Camp users
- Improves system reliability during the boot process

To complete the firmware update process, please follow the instructions in the updater application (/Applications/Utilities/MacPro EFI Firmware Update.app). The updater will launch automatically when the installation is complete.

For more information about firmware updates for Intel-based Macs, please visit:

<http://support.apple.com/kb/HT1557>
